

F-11.63

Station	KE #	Feature Description	Depth to Bedrock (ft.)	Approx. Cut or Fill Depth (ft.)	Boring Logs Available	Action	Notes
24+26, 35' RT	1	Large Shallow Depression ~20'x30'	12	-6.2	Y	NFA	No inwash, stiff soils
28+26, 50' RT	2	Small Depression ~10'x8'x1'	20	+6.2	Y	NFA	No inwash, stiff soils
32+82, 128' RT	3	Sinkhole ~11'x15.5' and 90' W of CL (w/in ROW), Void channeling soil removal can be seen at bottom.	7.2 to 13.5	+6.5	Y	Sec. 6.7	Graded Filter Recommended
26+81, 263' RT	4	Small Depression ~2'x5'	Unknown	N/A	N	NFA	Outside of right of way
23+08, 208' RT	5	Egg Shaped Open Void ~6'x10', Filled w/ rubble and debris	8.0	N/A	N	NFA	Outside of right of way
33+58, 1505, RT	6	2'x5'x1' depression	Unknown	N/A	N	NFA	Outside of right of way
38+08, 29' RT	7	Small Depression ~5' in dia.	7.5	-8.3	Y	NFA	No inwash and cut depth equal to bedrock
39+95, 88' RT	8	Small Depression ~5'x8'	15.3	-8.5	Y	NFA	No inwash, stiff soils
42+22, 137' LT	9	Depression ~7'x8'x1.5'	8.3	-0.8	Y	NFA	No inwash, stiff soils
54+00, 92' RT	10	Spring for the Workman Branch	Surface?	N/A	N	Sec. 6.6	Spring box recommended
55+20, 43' RT	11	Large Shallow Depression ~14'x16'	7.5	+29.1	Y	NFA	No inwash, stiff soils
63+07, 22' LT	12	Small Depression ~6' in dia.	17.5	-3.7	Y	NFA	No inwash, stiff soils
70+70, 66' RT	13	Small Open Void ~1'x2'x2'	12.2 to 19.5	-3.9	Y	Sec. 6.8	Fill present in possible collapse
71+80, 24' RT	14	Small Depression ~1'x2' within discolored patch of grass	16.6 to 31.1	-3.7	Y	Sec. 6.8	Large pinnacle sloping west
100+14, 145' RT	15	Circular Depression ~3' in dia. & 1.5' deep	Unknown	N/A	N	NFA	Outside of right of way
139+85, 10' RT	16	Oval Depression ~5'x15'	0 to 47.0	N/A	Y	Sec. 6.10	Completed Geophysics
137+24, 154' RT	17	Circular Depression ~4' in dia. And 1' deep	Unknown	N/A	N	NFA	Outside of right of way
140+22, 175' RT	18	Shallow Circular Depression ~3' in dia.	Unknown	N/A	N	NFA	Outside of right of way
141+80, 516' RT	19	Recent Collapse, Cave, Extent Undetermined	Surface	N/A	N	Sec. 6.9	Completed Geophysics
141+59, 381' RT	20	Circular Depression ~70' in dia.	Unknown	N/A	N	NFA	Outside of right of way
108+28, 308' RT	21	Cave, Extent Undetermined	Surface	N/A	N	Sec. 6.9	Completed Geophysics
120+07, 4' RT	22	Large Shallow Depression ~20'x35'	33.3	-20.4	Y	NFA	No inwash, stiff soils, surrounding borings also have deeper bedrock
126+85, 92' LT	23	Large Shallow Depression ~12'x15'	19.5 to 30.0	-10.6	Y	NFA	No inwash, stiff soils, pinnacled bedrock
108+97, 61' RT	24	< 1' dia. collapsed conduit in exposed bedrock	Surface	-21.6	N	Sec. 6.5	No further action
113+44, 25' RT	25	Spring in unnamed tributary of Ward Branch	Surface	+8.1	N	Sec. 6.6	Spring box recommended
117+92, 8' LT	26	Circular depression ~ 6' diameter & 1' deep	19.5	-22.5	Y	NFA	No inwash, stiff soils
N/A	27	Riverbluff Cave	N/A	N/A	N	NFA	South Entrance (southern most point)

Red Text = Refer to Section in Report

NFA = No Further Action